




SL-095 Assembly instructions


A



D



B




C



Sen



Time
Min 7sec
Max 5min



2.8m

1.8-2.5m

110°

E

